

Sale Name: AUTOMOTIVE AUCTION - TUESDAY SEPTEMBER 19, STARTS AT 12 NOON

LOT 98 - 2016 Hyundai ELANTRA



VIN 5NPDH4AE0GH656577

YEAR 2016

MAKE Hyundai

MODEL ELANTRA

ENGINE 1.8

DRIVETRAIN FWD

FUEL TYPE Gas

TRANSMISSION AUTOMATIC

FUEL TYPE GAS

MILEAGE 162,202 KM

SPEEDOMETER KM

ODOMETER KM

ENGINE LIGHT NO

PLATE NUMBER NONE

PLATE DATE N/A

MVI 06/22

FEATURES PWR WINDOWS, PWR LOCKS , PWR MIRRORS, CRUISE CONTROL, TILT, HEATED SEATS

AIR CONDITIONING/HEAT AC FUNCTIONING, HEAT FUNCTIONING

TECHNOLOGY CD PLAYER, SUBSCRIPTION BASED SATELLITE RADIO, BLUETOOTH, HANDS FREE CALLING

SEATING STANDARD SEATING

BODY 4 DOOR

INTERIOR TRIM CLOTH

INTERIOR CONDITION GOOD

INTERIOR COMMENTS Seats/carpet stains

ODOR Cigarettes

EXTERIOR CONDITION GOOD

EXTERIOR - COMMENTS Left front fender dented/paint peeling/taped to front bumper, left front door dented/rubbing against left front fender when opening and closing, left front door scratches, left rear door dent/paint chips, glue residue on trunk lid, right rear door dent/paint chips, front bumper scratches/license plate holes/ rust, hood chips, left side of front bumper taped to left front fender, missing left front fog light, headlight broken/taped.

TIRE COMMENTS (BASED ON CENTER OF TIRE) Front tires 40%, 205/60/16, rear tires 50%, 205/60/16

KEYS NO KEYS

COLOUR WHITE

DECLARATION ENGINE STARTS WITH A BOOST, REQUIRES VENDORS APPROVAL

SALES STATUS GREEN LIGHT

SALES CATEGORY REPOSSESSION

Description

BANK REPOSSESSION

ENGINE STARTS WITH A BOOST. DAMAGE TO FRONT BUMPER LEFT SIDE/LEFT FRONT FENDER, HEAD LIGHT, MISSING LT FOG LIGHT

[CLEAN CARFAX](#)

ENGINE LIGHT NO

DECLARATION ENGINE STARTS WITH A BOOST, REQUIRES VENDORS APPROVAL

SALES STATUS - GREEN LIGHT

SALES CATEGORY - REPOSSESSION

Quantity: 1



<https://jardine.auctioneersoftware.com/>